



# Flexco® Cracking Chisel




- Replacement of prematurely worn plates in minutes without replacing entire splice.
- Requires only a hammer.
- Three sizes available.  
C1C for No. 1, 140 or 190 nuts  
C2C for No. 1-1/2, 2 or 2-1/4 nuts.  
C3C for No. 2-1/2 and 3 nuts

With the Flexco® Cracking Chisel, excessively worn top plates and individual fasteners can be replaced quickly and easily. Only a hammer and a Flexco® Cracking Chisel are required. Removal of prematurely worn plates avoids installing a complete new splice. Saves time and money. Two simple steps.



1. Place Cracking Chisel over the nut and hit with a firm blow. Use a 2 lb. or heavier hammer. Be sure to wear safety goggles. **NOTE:** Position worn plate over solid backing before striking chisel.



2. After nuts are removed, replace plates, bolts, and nuts. Tighten nuts and break off excessive bolt ends. **NOTE:** Tighten nuts so plates compress into belt cover and pucker belt around plate edge.