30018RPR – CEBC1 Refurbish / 30001RPR – EBC1 Refurbish

Tool Repair Sheet

During the refurbishment process, the EBC1/CEBC1 is completely disassembled, and all components are inspected for wear. Certain components are replaced regardless of their condition. During refurbishment, the entire tool is cleaned and worn components are replaced to make it operable again.

DESCRIPTION	QUANTITY	PART EXPLANATION
Bearing 6200 Sealed	4	Guides the tool along the work surface and belt
SHCS M8 X 40MM Stainless	4	Bearing Assembly Hardware
SHCS M10 X 50MM Stainless	1	
SHCS M10 X 60MM Stainless	1	
Locknut M8 Stainless	4	
Locknut M10 Stainless	4	
Washer M8 Stainless	10	
Washer M10 Stainless	8	
Spacer EBC/CEBC	1	
SHCS M10 X 30MM 18-8 SS	2	
Blade EBC1	1	Belt Cutting Blade
Bearing 608 Sealed	8	Supports and guides the blade to prevent deflection

THESE COMPONENTS ARE ALWAYS REPLACED

*Other components – including the tool body itself – are not replaced during normal refurbishment.

