



Partners in Productivity

Application Profile

Flexco Load Zone Solutions Contain Dust At Aggregate Operation

Industry

Aggregate

Application

Crusher Load Zone

Product

Urethane Skirting

Objective

- Control spillage and dust
- Minimize maintenance time

Conveyor Detail

Belt width 1200mm, 3 ply belt, 600PIW rating handling minus 150mm material



Problem:

Spillage has always been a problem for a Midwest aggregate operation and the solution they were using wasn't performing as efficiently as they had hoped. The maintenance team was using 12mm x 150mm rubber sheeting to try to seal under a transfer point that was hard to service, causing a housekeeping nightmare. The rubber had to be changed out every two weeks in an attempt to contain the material. This caused material buildup and increased time spent cleaning since one side of the conveyor was against the structure and couldn't be easily accessed.

Solution:

When a Flexco representative gave the maintenance supervisor a half roll of Flexco Urethane Skirting, he was skeptical that there was a better, less expensive way to manage spillage. He installed it and waited for the results.

Result:

There was an immediate decrease in maintenance trips for clean up, and the skirting ran for more than two months without adjustment and spillage. Not having to replace the rubber sheeting is saving the plant approximately \$10,000 a year. The maintenance supervisor was so impressed that he is replacing all the 12mm rubber skirting to urethane throughout the plant, and he is treating other problem areas with the urethane solution.

240 Macpherson Road • #02-01 • Singapore 348574
Tel: +65-6484-1533 • Fax: +65-6484-1531 • E-mail: asiasales@flexco.com

Visit www.flexco.com for other Flexco locations and products.